


# K50APFF100GRE Pick-to-Light – Placement Sensor Diffuse Mode Sensor with Fixed-field Background Suppression




#### Technical data

_	
Type	K50APFF100GRE
ID	3075805
Signal and display data	
Purpose	Pick-to-Light
Function	Diffuse mode sensor with fixed-field back- ground suppression
Max. range	100 mm
Light type	IR
Number of beams	1
Switch Function	Momentary
Features of color 1	Green, Permanently on
Features of color 2	Red
Special features	Wash down
Electrical data	
Operating voltage U <sub>B</sub>	1230 VDC
DC rated operating current I <sub>e</sub>	≤ 150 mA
Max. current consumption per color	75 mA
Output function	NO contact, PNP
Input type	PNP
Response time typical	< 3 ms
Mechanical data	
Design	Dome, K50
Dimensions	Ø 50 x 56.8 mm
Housing material	Plastic, PC, Black
Window material	Polycarbonate, diffuse

#### **Features**

- Protection class IP67
- Cable: 2m
- Fixed background suppression at 100 mm
- ■Job light: green
- Mispick: red
- ■Actuation: not signalled
- Operating voltage 12...30 VDC
- ■PNP switching
- ■NO contact

#### Wiring diagram



### Functional principle

The K50 pick-and-place sensor is suitable for many mounting and component placement applications. The green work light or other signal lights are reflected perfectly by the entire dome (depending on the version). The transistor output can be easily connected to a system control, which is programmed for a special task sequence. The work light of the sensor is located in or next to every bin at the operator's workstation and indicates: 1. The bins with the components to be picked up for a particular work step and 2. the sequence in which the components have to be picked up. If the operator removes a part from the bin, the K50 detects the hand in the bin and sends a signal to the control unit. The system then checks if the correct component has been picked up and - depending on the configuration - switches the corresponding work light off and the next one on, according to the assembly sequence. The work sequence control leads to increased efficiency, improved quality control and reduces rework and testing expenses. The term work light therefore refers to the visual indicator of the bin from which a part should be removed next. The actuation indicator confirms the removal with a different color. The mispick indicator illuminates if a bin was reached into when the work light was not



3052521

# Technical data

Electrical connection	Cable, 2 m, PVC
Number of cores	4
Ambient temperature	-40+50 °C
Relative humidity	090 %
Protection class	IP67 IP69
Tests/approvals	
MTTF	146 years acc. to SN 29500 (Ed. 99) 40 °C
Approvals	CE, cULus listed

## Accessories

SMB30A	3032723
	Mounting bracket, rectangular, stainless steel, for sensors with 30mm

Mounting bracket, PBT black, for sensors with 30 mm thread, rotatable





SMB30SC

